



FIGURE 3
780215

THIS POSITION PREVENTS ACTIVATION OF THE LIFT AXLE SERVICE BRAKES WHEN THE LIFT AXLE(S) ARE IN THE UP POSITION.

VALVE SHOWN WITH LIFT AXLE(S)
IN THE UP POSITION